

Mount McKinley Headquarters, Employee Residence
(Mount McKinley Headquarters, Superintendent's Garage)
(Mount McKinley Headquarters, Building No. 111)
Denali National Park and Preserve
McKinley Station
Yukon-Koyukuk Division
Alaska

HABS No. AK-35-M

*HABS
AK,
23-MCKIN,
1-M-*

PHOTOGRAPH
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
REDUCED COPY OF MEASURED DRAWING

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, DC 20013-7127

HABS
AK,
23-MCKIN,
1-M-

ARCHITECTURAL DATA FORM

STATE ALASKA	COUNTY YUKON-KOYUKUK DIVISION	TOWN OR VICINITY MCKINLEY STATION
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Mount McKinley Headquarters (National Park Service files)		HABS NO. AK-35 M
SECONDARY OR COMMON NAMES OF STRUCTURE Employee Residence; Superintendent's Garage; Building #111		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) Denali National Park & Preserve		
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1939 (NPS files)	ARCHITECT(S) (INCLUDE SOURCE) National Park Service (NPS files)	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Severely charred by fire that destroyed the Superintendent's residence in 1939 while still unfinished, the building was repaired in 1940 and converted to the second administration building in 1944, replacing the first. In 1957 it became the Chief Ranger and Naturalist's office following Park tradition of conversion and change of usage.		
STYLE (IF APPROPRIATE) Rustic		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) log, poured concrete, stone veneer, corrugated metal		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) L shaped; 24'6" x 33'6" and 15'6" square; one story		
EXTERIOR FEATURES OF NOTE		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES addition constructed on west wall in 1943; infill of garage doors on east wall; interior repartitioning, 1943; interior remodeling in 1960 and early 1980's; new metal roof, 1984		
PRESENT CONDITION AND USE single family residence good condition		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) NPS files; See Bibliography HABS AK-35		
COMPILER, AFFILIATION Sandra M. Faulkner, Historian, National Park Service		DATE June 26, 1986